## UNITED STATES PATENT AND TRADEMARK OFFICE **CERTIFICATE OF CORRECTION**

PATENT NO.

: 7,092,794 B1

Page 1 of 1

DATED

APPLICATION NO.: 09/679853

: October 5, 2000

INVENTOR(S)

: Mark Alexander Hill et al.

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

## TITLE: METHOD AND APPARATUS FOR CONNECTING TO HVAC DEVICE

- in Column 6, Line 23. The reference to "said server" is incomplete and should be replaced with --said server; on demand in order to detect a problem associated with the monitoring of the at least one HVAC device as well as to detect any problems with the monitored device itself;--.
- in Column 6, Line 55. The reference to "entry device" is incomplete and should be replaced with --entry device; on demand in order to detect a problem associated with the monitoring of the at least one HVAC device as well as to detect any problems with the monitored device itself;--.
- in Column 8, Line 3. The reference to "status information; and" is incomplete and should be replaced with --status information; on demand in order to detect a problem associated with the monitoring of the at least one HVAC device as well as to detect any problems with the monitored device itself--.

Signed and Sealed this

Fourteenth Day of November, 2006

JON W. DUDAS Director of the United States Patent and Trademark Office